


SPEED DATA ANALYSIS

Location



CENTRAL AVENUE
BARDON STREET
Latitude: 40.763504
Longitude: -74.408417



Analysis Time Period



Start	End
8/30/2021 1:31 PM	9/13/2021 9:41 AM

Vehicles Analyzed



15,069

Peak Time of Violations



8/30/2021
3:31 PM

Speed Limit



30

Enforcement Tolerance



10

Total Enforceable Violations



634

% Enforceable Violations



4%

Average Speed



30

Fastest Speed



64

SPEED DATA ANALYSIS

Slowest Speed

85th Percentile Speed



8



37

Enforcement Rating

LOW

Speed Enforcement Evaluator

Location

CENTRAL AVENUE

Total Percentage of Enforceable Violations


Closest Cross Street

BARDON STREET

Posted Speed Limit 30 MPH
Enforcement Tolerance 10 MPH
Enforcement Limit Greater than 40 MPH

GPS

Latitude: 40.763504
Longitude: -74.408417




Percent Speeding: 4%
Rating: Low

Analysis Dates

Start: 8/30/2021
End: 9/13/2021

Equipment Used

JAMMAR RADAR RECORDER



Percent Speeding: 2%
Rating: Low

Percent Speeding: 6%
Rating: Low

Installed By

CPL. DIROCCO #148

Vehicle Totals - Combined

<= 3	<= 6	<= 9	<= 12	<= 15	<= 18	<= 21	<= 24	<= 27	<= 30	<= 33	<= 36	<= 39	> 39
0	0	14	276	660	547	457	819	1011	1764	2862	3098	2187	1376
85th Percentile: 36.9													

Vehicle Totals - South, 1

<= 3	<= 6	<= 9	<= 12	<= 15	<= 18	<= 21	<= 24	<= 27	<= 30	<= 33	<= 36	<= 39	> 39
0	0	11	221	287	149	174	311	472	879	1455	1353	816	381
85th Percentile: 35.9													

Vehicle Totals - North, 2

<= 3	<= 6	<= 9	<= 12	<= 15	<= 18	<= 21	<= 24	<= 27	<= 30	<= 33	<= 36	<= 39	> 39
0	0	3	55	373	398	283	508	539	885	1407	1745	1371	995
85th Percentile: 37.9													