

Speed Enforcement Evaluator

Location

ELM STREET

Total Percentage of Enforceable Violations

Closest Cross Street

PARK AVENUE

Posted Speed Limit 25 MPH
 Enforcement Tolerance 10 MPH
 Enforcement Limit Greater than 35 MPH

GPS

Latitude: 40.764408
 Longitude: -74.420181

Analysis Dates


Start: 12/13/2022
 End: 12/24/2022

Equipment Used


JAMAR RADAR RECORDER

Installed By

CPL. DIROCCO #148



Percent Speeding: 24%
 Rating: Medium Low



Percent Speeding: 20%
 Rating: Medium Low

Percent Speeding: 27%
 Rating: Medium Low

Vehicle Totals - Combined

<= 3	<= 6	<= 9	<= 12	<= 15	<= 18	<= 21	<= 24	<= 27	<= 30	<= 33	<= 36	<= 39	> 39
0	0	22	216	698	391	336	607	1586	2979	4131	3570	2093	1184
85th Percentile: 36.9													

Vehicle Totals - South, 1

<= 3	<= 6	<= 9	<= 12	<= 15	<= 18	<= 21	<= 24	<= 27	<= 30	<= 33	<= 36	<= 39	> 39
0	0	15	16	88	99	152	333	888	1560	1847	1453	754	372
85th Percentile: 35.9													

Vehicle Totals - North, 2

<= 3	<= 6	<= 9	<= 12	<= 15	<= 18	<= 21	<= 24	<= 27	<= 30	<= 33	<= 36	<= 39	> 39
0	0	7	200	610	292	184	274	698	1419	2284	2117	1339	812
85th Percentile: 37.9													

SPEED DATA ANALYSIS

Location



ELM STREET
PARK AVENUE
Latitude: 40.764408
Longitude: -74.420181

Analysis Time Period



Start End
12/13/2022 12/24/2022
3:20 PM 5:05 AM

Vehicles Analyzed



17,812

Peak Time of Violations



12/20/2022
4:20 PM

Speed Limit



25

Enforcement Tolerance



10

Total Enforceable Violations



4,279

% Enforceable Violations



24%

Average Speed



31

Fastest Speed



70

SPEED DATA ANALYSIS

Slowest Speed

85th Percentile Speed



7



37

Enforcement Rating

HIGH